

APPENDIX B
SITE PHOTOGRAPHS

Phase I Environmental Site Assessment

Timberline Church ■ Fort Collins, Colorado

Photos Taken: November 2, 2018 ■ Terracon Project No. 20187108



1. View of site (facing southwest).



2. View of paved parking lot located on the southwest portion of the site (facing west).



3. View of site (facing north).



4. View of former CSU Agricultural Research Facility to the adjacent west of the site (facing west).



5. View of Foothills Channel to the adjacent south of the site, followed by multi-family residential property to the south (facing south).



6. View of multi-family residential property to the adjacent south (facing south).

Phase I Environmental Site Assessment

Timberline Church ■ Fort Collins, Colorado

Photos Taken: November 2, 2018 ■ Terracon Project No. 20187108



7. View of drainage basin and associated culverts and overflow riser, located along the southeastern portion of the site (facing north).



8. View of northern portion of property followed by multi-family residential property to the adjacent north of the site (facing north).



9. View of eastern portion of property followed by multi-family residential property to the adjacent east of the site (facing southeast).



10. View of Timberline Church and associated parking located to the adjacent north and west of the site (facing northwest).



11. View of concrete lined drainage ditch located along the eastern boundary of the site (facing northeast).



12. View of single-family residential properties located to the southeast of the site (facing southeast).